



NEWS

Contact: George Gilbert
313-248-8639

Ford Collision
Parts Hotline
cphelp@ford.com

IMMEDIATE RELEASE

FORD UPDATES PARTS/ADDS PART LINE TO COLLISION TRUCKLOAD PROGRAM

DEARBORN, Mich., May 1, 2008 – Ford Motor Company’s Ford Customer Service Division (FCSD) is continuing to drive down the cost of collision repairs by adding 45 new parts to its “Truckload Program” which offers deep discounts to Ford and Lincoln Mercury dealers and repair shops that purchase in bulk quantities.

More than 360 popular collision repair parts are part of the program. The 45 new parts, including grilles, fascias, mirrors, exterior lights and steel bumpers, are available at discounts of as much as 22 percent off list prices.

“The program improves with additional product and features each year,” said George Gilbert, Truckload Program manager for FCSD. “The feedback from our dealers, repairers and insurers enables us to continually help reduce repair cycle time and lower overall collision repair costs.”

The list price reductions, in combination with reduced packaging costs, are passed on to all collision repair shops that purchase the high-volume truckload parts through participating Ford, Lincoln and Mercury dealers.

For more information on the Truckload Program or its offerings, contact your local Ford, Lincoln and Mercury collision parts wholesaling dealer or the Ford Collision Parts Hotline at cphelp@ford.com.

The following charts detail the part numbers added to the program:

April 1, 2008 Additions to Collision Truckload Program

| Wheels | MY | Vehicle | Part Description |
|----------------|-----------|----------------|-------------------------|
| 3S4Z-1007-ABCP | 04-08 | Focus | Aluminum Wheel |
| 3W7Z-1007-FCP | 03-05 | Grand Marquis | Aluminum Wheel |
| 4F1Z-1007-CACP | 04-07 | Taurus/Sable | Aluminum Wheel |
| F8UZ-1015-BACP | 00-99 | Econoline | Steel Wheel |

| Header Panels / GOR-GOPs | MY | Vehicle | Part Description |
|---------------------------------|-----------|------------------------|-------------------------------|
| 3W3Z-8190-AACP | 03-06 | Grand Marquis | Radiator Grille Opening Panel |
| F7UZ-8A284-AACP | 97-08 | Econoline | Radiator Grille Opening Panel |
| F81Z-8A284-AACP | 03-04 | F-Series OVER 8500 GVW | Radiator Grille Opening Panel |
| XF2Z-8A284-AACP | 01-03 | Windstar | Radiator Grille Opening Panel |
| 2L1Z-8A284-AACP | 03-07 | Expedition | Radiator Grille Opening Panel |

| Valances / Deflectors | MY | Vehicle | Part Description |
|------------------------------|-----------|-------------------------|-------------------------|
| XL3Z-17626-ABCCP | 00-07 | F-Series UNDER 8500 GVW | Front Valance Panel |

| Mirrors | MY | Vehicle | Part Description |
|-----------------|-----------|-------------------|-------------------------|
| 6S4Z-17682-AACP | 04-08 | Focus (NAAO) C170 | Right Hand Mirror |
| 6S4Z-17683-AACP | 04-08 | Focus (NAAO) C170 | Left Hand Mirror |

| Lighting | MY | Vehicle | Part Description |
|-----------------|-----------|----------------|-------------------------|
| 4R3Z-13008-AACP | 05-07 | Mustang | Right Head Lamp |
| 4R3Z-13008-ABCP | 05-07 | Mustang | Left Head Lamp |
| 6L1Z-13008-AACP | 05-07 | Expedition | Right Head Lamp |
| 6L1Z-13008-BACP | 05-07 | Expedition | Left Head Lamp |
| 6L5Z-13008-AACP | 05-07 | Ranger | Right Head Lamp |
| 6L5Z-13008-BACP | 05-07 | Ranger | Left Head Lamp |
| 1L5Z-13200-AACP | 01-03 | Explorer Sport | Right Parking Lamp |

| Lighting cont'd | MY | Vehicle | Part Description |
|------------------------|-----------|----------------------|-------------------------|
| 1L5Z-13201-AACP | 01-03 | Explorer Sport | Left Parking Lamp |
| 2L1Z-13404-ABCP | 03-07 | Expedition | Right Tail Lamp |
| 2L1Z-13405-ABCP | 03-07 | Expedition | Left Tail Lamp |
| 5L3Z-13404-CACP | 04-06 | F150/Lincoln Mark L | Right Tail Lamp |
| 5L3Z-13405-CACP | 04-06 | F150/Lincoln Mark L | Left Tail Lamp |
| 2M5Z-15200-ABCP | 07-08 | Escape/Mariner/HYB | Fog Lamp |
| XL2Z-15200-AACP | 00-01 | Explorer/Mountaineer | Right Fog Lamp |
| XL2Z-15200-BACP | 00-01 | Explorer/Mountaineer | Left Fog Lamp |
| 1L5Z-15A201-AACP | 00-06 | Ranger | Right Head Lamp |
| 1L5Z-15A201-BACP | 00-06 | Ranger | Left Head Lamp |

| Isolators / Impact Pads / Bars | MY | Vehicle | Part Description |
|---------------------------------------|-----------|-------------------------|-------------------------|
| YF1Z-17754-AACP | 00-04 | Taurus/Sable | Isolator |
| XR3Z-17C947-AACP | 96-04 | Mustang | Isolator |
| XL3Z-17K833-AAACP | 99-04 | F-Series UNDER 8500 GVW | Impact Pad |
| 1L3Z-17K833-AAACP | 97-99 | F-Series UNDER 8500 GVW | Impact Pad |
| 3L3Z-17K833-AAACP | 98-04 | F-Series UNDER 8500 GVW | Impact Pad |

| Fascias | MY | Vehicle | Part Description |
|-------------------|-----------|---------------------------|-------------------------|
| 3L2Z-17K835-AABCP | 03-05 | Explorer Sport Trac | Rear Bumper Fascia |
| 6S4Z-17K835-HACP | 00-07 | Focus | Rear Bumper Fascia |
| 6S4Z-17K835-GACP | 02-07 | Focus | Rear Bumper Fascia |
| 2L7Z-17D957-EAACP | 03-07 | Lincoln Navigator | Front Bumper Fascia |
| 4L3Z-17D957-CACP | 04-05 | F150(P221)/Lincoln Mark L | Front Bumper Fascia |
| 5G1Z-17D957-AACCP | 05-06 | Taurus/Sable/Taurus X/500 | Front Bumper Fascia |
| 5R3Z-17D957-BAACP | 04-07 | Mustang S197 | Front Bumper Fascia |
| 6S4Z-17D957-DACP | 04-07 | Focus (NAAO) C170 | Front Bumper Fascia |

| Bumper Bars | MY | Vehicle | Part Description |
|--------------------|-----------|----------------------|-------------------------|
| 1L2Z-17906-AACP | 02-06 | Explorer/Mountaineer | Rear Bumper Isolator |

| Steel Bumpers | MY | Vehicle | Part Description |
|----------------------|-----------|---------------------------|-------------------------|
| 4L3Z-17906-GACP | 04-07 | F150(P221)/Lincoln Mark L | Rear Bumper Steel |
| 5C3Z-17757-BACP | 04-05 | Excursion | Front Bumper Fascia |

#

#

#